

~~SECRET~~

10

16.28

IN: 81420

25X1A6c

25X1A6c

25X1A6c

INFO

ONE

~~SECRET~~ 201700Z CITE [REDACTED] 2939

INFO [REDACTED]

25X1A2d2 IDEALIST [REDACTED] SCOPE PALLET OPERA LOGS

25X1A2d2 SUBJECT: REVIEW OF [REDACTED] CONFIG OPERATION.

1. ALL TAKE ACQUIRED DURING SCOPE PALLET HAS BEEN PROCESSED AND ALL EXPOSURES AND IMAGERY ARE EXCELLENT. THE CONFIG OPERATED NORMALLY ON ALL MISSIONS. THE ONLY EXCEPTION WAS THE MALFUNCTION OF A METERING ROLLER IN ONE OF THE TWO PANORAMIC CAMERAS. THE LAST 50 OF THE 1400 FEET OF TAKE ON MISSION 'ALPHA' WAS JAMMED. HOWEVER, THIS DID NOT AFFECT THE MISSION BECAUSE THE FLIGHT LINE WAS COVERED BY 4 OTHER CAMERAS. OF 25 TARGETS SCHEDULED, 8 WERE MISSED BECAUSE OF WEATHER, 2 OF THE TARGETS MISSED WERE PRIORITY 2, THE REMAINING 6 WERE PRIORITY 3. ALL PRIORITY 1 TARGETS WERE COVERED.

2. ON SITE FILM PROCESSING WAS EXCELLENT. AS EXAMPLE, ONE HOUR AFTER THE CONFIG HATCH WAS RELEASED UPON LANDING ONE ROLL OF FILM WAS PROCESSED AND IN THE HANDS OF OPERATIONS PERSONNEL. A PROTOTYPE PROCESSING TENT WAS INSTALLED IN THE HANGAR REQUIRING

~~SECRET~~

GROUP 3  
EXCLUDED FROM AUTOMATIC  
DOWNGRADING AND  
DECLASSIFICATION

IN: 81420

2939

~~SECRET~~

PAGE-2

APPROX 45 MINUTES FOR ERECTION. IT PROVED OF GREAT VALUE SINCE IT PROVIDED A HUMIDITY FREE ENVIRONMENT FOR PROCESSING THE TAKE AS WELL AS STORING THE CONFIG. PLANS ARE TO ADD FLUORESCENT LIGHTING AND A METHOD OF CLIPPING THE ELECTRICAL WIRES TO THE SUPPORT STRUCTURE. SOME SMALL LIGHT LEAKS WERE NOTED AND WILL BE REPAIRED LOCALLY.

3. HIGH HUMIDITY AND RAIN CAUSED SOME MOISTURE TO FORM ON THE INSIDE OF THE HATCH ON ONE MISSION. THIS WAS NOTICED WHEN INSTALLING THE HATCH COVERS. HOWEVER, SINCE IT DID NOT CAUSE ANY FOGGING OF THE TAKE DURING THE MISSION, IT IS CONCLUDED THAT IT ACCUMULATED AT LOW ALTITUDE JUST PRIOR TO LANDING. THE WEATHER WAS RAIN AND DRIZZLE AT THE TIME.

25X1A5a2  
25X1A5a2  
4. THE

PERFORMED IN AN OUTSTANDING MANNER DURING THE ENTIRE DEPLOYMENT. WHILE THIS WAS THE FIRST TIME THEY HAVE PARTICIPATED IN A DEPLOYMENT OPERATION, THEY IMMEDIATELY SET UP THEIR SHOP AND MAINTAINED AN OPERATIONAL READY CONFIG UNDER LESS THAN IDEAL CONDITIONS. THEY NEVER HESITATED TO ASSIST OTHER SECTIONS IN GETTING THE JOB DONE. THEY WOULD BE A WELCOME ADDITION TO THIS ORGANIZATION ANY TIME, ANY PLACE.

25X1A5a2

5. REQUEST PLEASE PASS INFO TO

~~SECRET~~

TOR: 201751Z DEC 67

25X1A6c

25X1A2d2